



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

June 14, 2012

Reviewed: 

Mine Name: Nielson Sandstone	Permit Number: M/023/0012
Operator Name: Ash Grove Cement Company	Inspection Date: June 13, 2012
Inspector(s): Wayne Western	Time: 10:30 – 10:45 am
Other Participants: Josh Nelson, Gordon Jarrett	Mine Status: Active
Weather Condition: Clear sky 80's	Last Inspection: July 14, 2011
Bond Renewal Date: June 8, 2013	Bond Amount: \$1,332,126
Surface Ownership: BLM	Mineral Ownership: BLM
Last Year of Production: 72,512 tons	Acreage: 132 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond is adequate and will be escalated in 2013.

The permit consists of the original permit plus some amendments that were not incorporated into the original permit. The Permittee agreed that the permit needs to be brought up to date. They agreed to meet with the Division and bring the NOI up to date.

The permit fees and annual reports are up to date.

The site is clear and in good repair. The Permittee uses the site to store slag (iron containing material) as well as to mine sandstone.

Conclusions and Recommendations:

The Division and the Permittee should work together to get the NOI updated.

Directions to Site:

The turnoff road to the site is approximately 4.7 miles north of the Leamington Cement Plant.

Inspector's Signature

WHW:

cc: (OPERATOR)


Jerry Mansfield, BLM

O:\M023-Juab\M0230012-NielsonSSQuarry\Inspections\INSP-06132012.doc

A handwritten signature in blue ink, appearing to read "Wayne Walters", is written over a horizontal line.



Sandstone operation



Slag pile



Drill rig on site



Truck used to transport slag